

1/16

PRESSURIZING DISK

Figure 1




Figure 2






Figure 3



4/16

Figure 4



5 / 16

Figure 5




Figure 6

6/16





Figure 7



8 / 1 6

Figure 8




Figure 9

9 / 1 6




Figure 10

10/16





Figure 11

11/16

a) SINTERING OF THICK PORTION



b) SINTERING OF THIN PORTION





Figure 12

12/16

a) When the Terminal Assembly is thick, the difference between T1 and T2 is large.



b) When the Terminal Assembly is thin, the difference between T1' and T2' is small.






Figure 13



14/16

Figure 14



15/16

Figure 15




Figure 16

